




Contact Pressure Stress Outlines-1




Contact Friction Stress-1



Contact Total Stress-1




Model-joints (with washer)



Solution-Joints(with washer)

Constraints and Loads Applied



Pretension force on bolt-2

